



Ramón L. Falcón 1851
(1684) El Palomar
Provincia de Buenos Aires
Argentina
Phone: 54-11-4659-0233 / 4976 / 5045
Fax: 54-11-4650-0233 / 4976 / 5045
administracion@espel.com.ar
www.espel.com.ar

Productos fabricados / Manufactured Products

Automatic starter switch / CDI for motorcycles and atv / Coils for motorcycles and atv / Condensers / Contact points / Electronic flashers / Electronic timers / Ignition coils / Motorcycle and atv sensors / Relays / Solenoids / Voltage regulators for motorcycles and atv

Marcas / Brands

DZE

Certificaciones / Certifications

EAQF / ISO 9001 / QS 9000

Clientes / Customers

Aftermarket / Autoparts companies / Ford Argentina S.C.A. / Peugeot Citroën Argentina S.A.

Exportaciones / Exports

Chile / Colombia / Uruguay / Venezuela

Productos comercializados, fabricados por terceros y/o importados / Products sold, manufactured by other companies and/or imported

Alternators / Boot drive / Horns / Ignition coils / Ignition modules / Lamps / Lamps for motorcycles / Starter motors / Starters for motorcycles and atv / Stators for motorcycles and atv / Voltage regulators

Plantas / Plants

Ramón L. Falcón 1851, (1684) El Palomar, Provincia de Buenos Aires, Argentina,
Phone: 54-11-4659-0233 / 4976 / 5045, Fax: 54-11-4659-0233 / 4976 / 5045, administracion@espel.com.ar